

**Division of Waste Management
UST Section
Civil Penalty Assessments**

January 2016

Responsible Party	Facility Name	Violation(s)	Penalty Amount	Date Assessed
Jackie McCarter 3615 Dallas-Cherryville Hwy Dallas, NC	Kingsway 21 3403 Dallas-Cherryville Hwy Dallas, NC Gaston Co.	Violation of 15A NCAC 2L .0405 by failing to submit a Limited Site Assessment report.	\$5,235.16	1/27/16
Zander, Inc. 11960 McCormick Dr. Maxton, NC	Hamlet Food Mart 500 King St. Hamlet, NC Richmond Co.	Violation of 15A NCAC 2N .0302 by failing to comply with overfill requirements for one UST system, violation of 15A NCAC 2N. .0402 by failing to have a corrosion protection systems inspected triennially by a qualified cathodic protection tester for three UST systems, and violation of NC Session Law 2010-154 by failing to retrain a primary operator after violations were found at an inspection.	\$7,846.14	1/19/16
Joseph Larry Scott 1075 Horseshoe Bend Rd. Erwin, NC	J. L. Scott Property 1075 Horseshoe Bend Rd. Erwin, NC Harnett Co.	Violation of 15A NCAC 2L .0106(b) and (c) by failing to submit a Notification of Discharge report, violation of 15A NCAC 2L .0106(b), (c) and (f) by failing to perform initial abatement actions, and violation of 15A NCAC 2L .0106 (c) and 2L .0111 by failing to submit and Initial Assessment report.	\$17,107.00	1/29/16
Scotland-Graham Oil Company, Inc. 1044 20 th Avenue Lane N.W. Hickory, NC	Little Oil Company 10 3 rd Street S.E. Hickory, NC Catawba Co.	Violation of 15A NCAC 2N .0302 and .0402 by failing to meet corrosion protection requirements for one UST; violation of 15A NCAC 2N .0302 by failing to meet corrosion protection requirements for metal flexible connectors and other metal piping components associated with two UST systems; violation of 15A NCAC 2N .0801 by failing to secure and maintain two UST systems in temporary closure; and violation of NC Session Law 2010-154 by failing to provide a trained primary operator for two UST systems.	\$16,042.41	1/13/16